Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC. **Well Operator:** XTO ENERGY INC.

Well Name: ALLEN 21X-17 CENTRAL TANK BATTERY

Field Name: DOLLAR JOE Well File #:

 Date Incident:
 10/24/2015
 Time Incident:
 08:00
 Facility ID Number:
 218893-01

 County:
 WILLIAMS
 Twp:
 155
 Rng:
 96
 Sec:
 17
 Qtr:
 NE NW

Location Description: Combine Tank Battery (CBT)

Submitted By: Scot Richardson Received By:

Contact Person: Scot Richardson

P.O Box 6501

Englewood, CO 80155

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 40 Barrels 40 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

NONE

Areal Extent:

Potential Environmental Impacts:

NONE

Action Taken or Planned:

The free oil was collected and returned to the tank.

Wastes Disposal Location: No waste collect, all oil returned to tank.

Agencies Involved:

Updates

Date: 10/26/2015 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.